

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

FIG. 1




FIG. 2A




FIG. 2B




FIG. 3A




FIG. 3B




FIG. 3C




FIG. 4




FIG. 5




FIG. 6A




FIG. 6B

アンテナ (番号)	データ伝送速度
A1	450
A2	350
A3	250
A1	350
A2	400
A3	300
A1	250
A2	350
A3	405

FIG. 6C

$$1/450 : 1/350 : 1/250 = 22 : 29 : 40$$

$$1/350 : 1/400 : 1/300 = 29 : 25 : 33$$

$$1/250 : 1/350 : 1/405 = 40 : 29 : 25$$

FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12

ANT _SEL [0]	ANT _SEL [1]	ANT _SEL [2]	ANT _SEL [3]	ANT _SEL [4]	ANT _SEL [5]	ANT _SEL [6]	ANT _SEL [7]	ANT _SEL [8]	ANT _SEL [9]
アンテナ総数を7個と設定									

前方探索数:2 後方探索数:1とした場合

接続中									
RSSIで強度確認する範囲									

	接続中								
RSSIで強度確認する範囲									

					接続中				
RSSIで強度確認する範囲									

						接続中			
RSSIでの確認範囲									

FIG. 13

